	Type	L #	Hits	Search Text	DBs
1	IS&R	L1	1901	((310/52) or (310/53) or (310/55) or (310/58) or (310/61) or (310/60A)).CCLS.	USPAT
2	BRS	L2	885	<pre>1 and (sleeve tube ring cylinder)</pre>	USPAT
3	IS&R	L3	953	((310/52) or (310/53) or (310/55) or (310/58) or (310/61) or (310/60A)).CCLS.	US- PGPUB ; USOCR
4	BRS	L4	0	1 and (sleeve tube ring cylinder)	US- PGPUB ; USOCR
5	BRS	L5	545	3 and (sleeve tube ring cylinder)	US- PGPUB ; USOCR
6	BRS	L6 .	2694	(motor genearator dynamo) with cool\$4	EPO
7	BRS	L7	0	<pre>1 and (sleeve tube ring cylinder)</pre>	EPO
8	BRS	L8	459	6 and (sleeve tube ring cylinder)	EPO
9	BRS	L9 .	67	8 and rotor	EPO
10	BRS	L10	8768	(motor genearator dynamo) with cool\$4	JPO
11	BRS	L11	1108	10 and (sleeve tube ring cylinder)	JPO
12	BRS	L12	190	11 and rotor	JPO
13	BRS	L13	18106	(motor genearator dynamo) with cool\$4	DERWE NT
14	BRS	L14	3749	13 and (sleeve tube ring cylinder)	DERWE NT
15	BRS	L15	639	14 and rotor	DERWE NT

	Time Stamp	Comments	Error Definition	Err
1	2005/06/16 09:29		•	
2	2005/06/16 10:00			
3	2005/06/16 09:29		,	
4	2005/06/16 09:29			
5	2005/06/16 09:59		·	
6	2005/06/16 10:08			
7	2005/06/16 10:01			
8	2005/06/16 10:08		,	
9	2005/06/16 10:08			
10	2005/06/16 10:17			
11	2005/06/16 10:17			
12	2005/06/16 10:18			
13	2005/06/16 10:17			
14	2005/06/16 10:18			
15	2005/06/16 10:18			

	Туре	L #	Hits	Search Text	DBs
16	BRS	L16	177	15 and axial\$4	DERWE NT

	Time Stamp	Comments	Error Definition	Err
16	2005/06/16 10:19			